

Optional Parts for the DAMPER ZZ-R Front Pillow-ball Upper Mount with Camber Adjustability is now available for the TOYOTA GR YARIS 2024/Ó4- (GXPA16)





Click here for further information on the DAMPER ZZ-R

Product Description

- Front Pillow Ball Upper Mount for the GR YARIS 2024/04-
- The original reinforced rubber upper mount on the ZZ-R can be easily changed to the optional pillow ball mounts.
- The front upper mount is converted to a pillow-ball structure allowing the front camber angle to be adjusted.
- Estimate Camber adjustment range : -5°00'~-1°40' (Adjustment range will vary when DSC Plus is installed)
- Fine tune the alignment for enhanced traction, cornering grip and stability.
- By changing the front upper mount to pillow-ball, information from the road surface is directly delivered to the driver for enhanced response.
- Additionally, by adjusting the front camber angle, the alignment can be precisely dialed to improve traction.

(Vehicle)	(Model Year)	(Model)	(Engine Model)	(Compatible Code No.)
TOYOTA				
GR YARIS	2024/04-	GXPA16	G16E-GTS	92647,98647

■ Remarks

- · Compatible with AT/MT. Compatible with all grades.
- · Can be installed along with DSC PLUS. Please review compatibility chart for further information.
- · Suspension must be removed to install upper mount.
- The length of the suspension will be altered after installation.

Please make adjustment to ride height accordingly. Ride height adjustability range will not change.

Product Information					
(Product Name)	(Code No.)	(JAN Code)	(Remarks)		
GR YARIS 2024/04- Front Pillow Ball Upper Mount	92647-FUPRP	4959094946472	Can be installed with 92647. Please review compatibility chart when using with DSC PLUS 98647		

Precaution during Installation

- Since the upper mount will become pillow-ball, noise from the suspension traveling over uneven surface will become more noticeable.
- Can be installed along with DSC PLUS. The adjustability range will be between (-4°00'~-2°30')
- When changing the upper mount, the suspension will need to be uninstalled, and the length of the suspension will need to be readjusted.